United States of America

Department of Transportation -- Hederal Abiation Administration

Supplemental Type Certificate

Number ST02763AT

This certificate issued to

Avionics Support Group, Inc. 13062 S.W. 133 Court Miami, FL 33186

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product--Type Certificate Number: A2NM

Boeing

Model: 757-200/-300

Description of Type Design Change: Installation of an In-Flight Cabin Video Surveillance System in accordance with Avionics Support Group, Inc. Master Drawing List 23485-MDL, Revision IR, dated 10 October 2003 or later FAA approved revision.

Limitations and Conditions: This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated, unless it is determine by the installer that the interrelationship between this change and any other previously approved modifications will produce no adverse effect upon the airworthiness of that airplane. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission. FAA approved Airplane Flight Manual Supplement for In-Flight Cabin Video Surveillance System dated November 24, 2003 is a required part of this STC.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: October 6, 2003

Date reissued:

Date of issuance: November 24, 2003

Date amended:

By direction of the Administrator

(Signature)

Eugene L. Bollin Associate Manager, ACE-116A Atlanta Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.